

Article Number: 255 | Rating: 5/5 from 1 votes | Last Updated: Wed, Jul 29, 2020 at 9:45 AM

Draytek have released a critical firmware update for the Vigor 3900 / 2960 / 300B. We recommend that you update the firmware to 1.5.1.1. The update is for Vigor 3900, 2960 and 300B only and does not affect any other Draytek product.

More information regarding security update is available [here](#):

<https://www.draytek.co.uk/support/security-advisories/kb-advisory-jun20>  
(<https://img.drayteknews.co.uk/3A5A97FB8D74F87CBA011CA5ADBB175206B512AA5BDB0F45BA25C700F3187E78/357AADB4C5E5D9CFFA9370747ECB2893/LE35>)

As with any such update, it is important that you upgrade any applicable models under your control immediately.

Posted by: Keira Tait - Wed, Jul 29, 2020 at 9:40 AM. This article has been viewed 1992 times.

Online URL: <https://kb.ic.uk/article/security-advisory-vigor-3900-2960-300b-router-vulnerability-july-2020-255.html> (<https://kb.ic.uk/article/security-advisory-vigor-3900-2960-300b-router-vulnerability-july-2020-255.html>)